Performance Evaluation Details

ID E1

Project Sewer System Cleaning and Manhole Camera Inspection Services

Project Number23ITB137397A-KMSupplierWoolpert, Inc.

Supplier Project Contact Beth Haun (preferred language: English)

Performance ProgramGoods and Commodity ServicesEvaluation Period08/01/2023 to 08/31/2023

Effective Date09/26/2023Evaluation TypeFormalInterview Date09/20/2023Expectations Meeting Date09/20/2023StatusCompleted

Publication Date 09/26/2023 10:02 PM EDT 10/09/2023

Completion Date 09/26/2023 10:02 PM EDT

Evaluation Score 79

Related Documents

There are no documents associated with this Performance Evaluation

OVERALL RATING GUIDE - GOODS AND COMMODITY SERVICES

Evaluation Score Range
Outstanding = 90-100%
Excellent = 80-89%
Satisfactory = 70-79%

Needs Improvement = 50-69%

Unsatisfactory = -50%

QUALITY OF PRODUCT OR SERVICE

17/20

Rating

Excellent: There are no, or very minimal, quality problems, and the

Contractor has met the contract requirements.

Comments Acceptable

TIMELINESS OF PERFORMANCE

14/20

Rating

Satisfactory: There are no, or minimal, delays that impact achievement of

contract requirements.

Comments Acceptable

BUSINESS RELATIONS 14/20

Rating

Satisfactory: Response to inquiries and/or technical, service,

administrative issues is consistently effective.

Comments Acceptable

CUSTOMER SATISFACTION 17/20

Rating

Excellent: Contractor representative communicates routinely with the
User Department, professional and responsive to User Department's request for

information.

Comments Acceptable

COST CONTROL 17/20

Rating

Excellent: Compliance with contract pricing, minor cost discrepancies identified by User Department that require explanation, quickly resolved cost/price

issues; compliance with invoice submission, corrections resolved quickly.

Comments Acceptable

GENERAL COMMENTS

Comments Good Contractor. Great Reports